
Γ

L


Stationary Armature Machine



١

Stationary Armature Machine

Fig 1C



Γ

Stationary Armature Machine

Fig 2A


┙

┌ Douglas Richard Customer No. 38019 Sheet 4 of 13 7

Stationary Armature Machine


Г

Fig 3



┙


Stationary Armature Machine



┙

Stationary Armature Machine


Fig 5



Stationary Armature Machine

Γ

Fig 6




Douglas Richard Customer No. 38019

Stationary Armature Machine

Г


Fig 7



Stationary Armature Machine

Г

Fig 8A



1

Γ

Stationary Armature Machine






Fig 9A




Stationary Armature Machine

 Γ



Stationary Armature Machine



Series Wound

Rotor

To Power Supply

Brush

Slip ring

Shunt

Douglas RichardCustomer No. 38019

Г

L

Stationary Armature Machine

Fig 13

